



Dust Control Activities Monthly Site Review

Report Type:

- Investigation summary
- Abatement/remediation summary
- Project update
- Site Clearance report

Additional Reports/information to follow?

- Yes No

Client: City of Scandia	Contact: Neil Soltis	Date of Investigation February 10, 2016
Project Name: Zavoral Mine Dust Emissions Monitoring		Report Date:
Project Location: Zavoral Mine, Scandia MN		Project # 4055-004
Project Description: Dust control monitoring and oversight during aggregate mining and hauling operations		

Task/Item	Completed as per DCP			Notes/Recommendations
	Yes	No	N/A	
Haul Road				
Paving - maintain first 300 feet	✓			
Asphalt millings - main haul road		✓		
Dust control application			✓	
Watering - as needed to control dust			✓	
Washing - at least 2x per day	✓			
Sweeping - 1-2 times per week	✓			DAILY - MULTIPLE TIMES
Tracking	✓			
Records	✓			
Excavation Area				
Watering - as necessary	✓			
Load equipment washed	✓			
Hauling Operations				
Covered trucks	✓			
15mph site speed	✓			
No idle >15 minutes	✓			
Trucks washed			✓	

Operations in compliance with Dust Control Plan? Yes No Other:

Findings/Recommendations/Actions: Temperature: 5-8° Wind: 5-8 MPH

DUST BUILDUP ON DRIVEWAY & AIRBORNE DUST WHEN DRIVING ON MAIN ROAD. SWEEPING OPERATIONS ARE KEEPING INTERSECTION & HWY CLEAN - VERY LOW AIRBORNE RELEASE

Remarks:
The environmental services provided by Indoor Environment Group's industrial hygienists, technicians and project managers for this project have been conducted in a manner consistent with the degree of care and technical skill exercised by environmental professionals currently practicing in this area under similar budget and time constraints. Recommendations contained in this report represent our professional judgment at the time the project was performed. This is only a summary of work performed. Following or implementing the recommendations presented should not be considered final completion or closure of this project. Additional work may be necessary to correct current and/or future problems. No warranty is implied or intended.

Summary Report Prepared/Submitted by: Dave Gutterud		Summary Report Review by:	
Title: Director of Operations	Phone number: 651-779-4300 x6	Title:	Phone number:
Signature: 		Signature:	